UPGRADE

- 1. Nightvision with dual screens, one of which is a 21" monitor on the bridge
- 2. New 46" flat screen TV in Salon with computer HTMI integration as a monitor
- 3. Surround sound
- 4. Stern thruster added to existing bow thruster
- 5. Pantry conversion of the 3rd bunkroom
- 6. Re designed and upholstered salon seating with 2 reclining seats on port side coach
- 7. Pull-out work desk in salon that spans 2 seats on the couch
- 8. Pull-out office set-up with printer, scanner and desktop computer in Salon
- 9. New high-back fold-down couch in bridge that makes into a queen size bed
- 10. Reconfigured and reupholstered couch/seat in cockpit
- 11. New carpeting on bridge
- 12. Upgraded cockpit canvas with see-through and easy open windows
- 13. Upgraded premium Ultra anchor 60 Kg
- 14. Upgraded batteries throughout
- 15. Inverter
- 16. In cockpit davit for dinghy on swim platform
- 17.AB RIB center console 2007 AB Dinghy with 40hp Nissan 4 stroke motor
- 18.HD TV and DirecTV equipment with 2 separate mother/slave set-ups (4 total monitors)
- 19. Upgraded radar and navigation software
- 20. Rebalanced and tuned props and applied PropSpeed 5/16
- 21. Internal WiFi upgrade with HotSpot xR-enhanced cell & extended wifi range
- 22. Redesigned and Reupholstered dinette seating
- 22.Upgraded mattress in guest bedroom
- 23. Stainless flag staff on bow
- 24. Bottom recently painted
- 25. Bird-Aweigh system for deterring birds from perching on the railings and hull
- 26.New bridge enclosure (9/16): Rainer front window; modified corner windows with Makrolon GP for > visibility; long length side panels for improved design and better integrity; and redesigned 2 stern windows to enable improved visibility & ability to easily open
- 27.Bennett Electronic Trim Tab Indicator Control
- 28. Upgraded upholstery and seat configuration on bridge
- 29. Flexiteek Synthetic flooring in cockpit
- 30. LED lights throughout including engine room
- 31. Upgraded cockpit seating with higher back
- 32. New bridge display for improved navigation and redundancy
- 33 Danforth FX -85 stern throw anchor with 100' of line and a swivel stainless attachment juncture.

34

35

VENDOR

Johnson-Hicks Sausalito

CostCo

Bose

Florida Bow Thrusters (Merritt Isl. Fla)

West Coast Canvas-Curt Page

QuickLine Ultra Anchor

Johnson-Hicks Sausalito

Johnson-Hicks Sausalito

Florida Bow Thrusters (Merritt Isl. Fla)

NW Inflatables Portland, Oregon

Johnson-Hicks Sausalito

Johnson-Hicks Sausalito

Thomas Prop

Johnson-Hicks Sausalito

West Coast Canvas-Curt Page

West Coast Canvas-Curt Page

Metropolis Metal Works-Alameda

Delta Marine

West Coast Canvas-Curt Page

West Coast Canvas-Curt Page

Delta Marine

West Coast Canvas-Curt Page

West Coast Canvas-Curt Page

J&H Marine

West Coast Canvas-Curt Page

Delta Marine

West Coast Canvas-Curt Page

West Coast Canvas-Curt Page

J&H Marine